Weathertzation Assistance Program

Work Order (Bid Form)

WORK ORDER INFORMATION

Work Order Name: 14014SO2325Work Order Type: WeatherizationAudit Name: 14014SO2325

CLIENT INFORMATION

Client Name: Address:

Client ID: 14014SO2325 SHELBYVILLE, TN 37160

Alt. Client ID: BEDFORD

AGENCY INFORMATION

Agency: SOUTH CENTRAL HUMAN RESOURCE AGENCY Agency Phone: (931) 433-7182

Address: 1437 WINCHESTER HIGHWAY Fax: (931) 438-0074

Company Name & License Number:	
Contractor's Signature:	

<u>COMMENT</u>

Client Name:
Client ID: 14014SO2325
Alt. Client ID: BEDFORD

Work Order (Bid Form)

Work Order Name: 14014SO2325 Report Run On: 5/28/2010 DOE Weatherization Assistant

Version 8.5.0 Page 1 of 5

	Itration Redctn	Components					Inspected	
REGIS CFMS 2. CLE	L DUCT WORK / USE M TERS TO READ 1.0 OR AN / SERVICE UNIT	LESS / RE	DUCE				5	
4. WHE BACK	LACE 2 MISSING FOUN ERE A PREVIOUS CEILII INSULATION, THIS NEE AND D/S FRONT AND E	NG REPAI DS TO BE	R WAS	,		RAKE	D	
				Estimated	<u> </u>		Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Miscellaneous Supplies	Infiltration Reduction	Each	1					
2 Labor	LABOR	Hour						
Other Detail								
]		
			Measur	e Sub Total:]	Sub Total:	
Field Notes:							L	
77074 7701007								
Measure 2 DW	/H Pipe Insulation ATE FIRST 2FT OF HOT	AND COL		Componen				Inspected
Measure 2 DW Comment INSULA	ATE FIRST 2FT OF HOT		D	Estimated	<u> </u>	Ofte	Actual	
Measure 2 DW Comment INSUL	ATE FIRST 2FT OF HOT Description / Comment	Units	D Qty	•		Qty		Inspected
Measure 2 DW Comment INSUL	ATE FIRST 2FT OF HOT		D	Estimated	<u> </u>	Qty	Actual	
Measure 2 DW	ATE FIRST 2FT OF HOT Description / Comment	Units	D Qty	Estimated	<u> </u>	Qty	Actual	
Measure 2 DW Comment INSULA # Material / Labor 1 Insulation	ATE FIRST 2FT OF HOT Description / Comment DHW Pipe Insulation	<i>Units</i> Each	Q ty 1	Estimated	<u> </u>	Qty	Actual	
Measure 2 DW Comment INSULA # Material / Labor 1 Insulation 2 Labor	ATE FIRST 2FT OF HOT Description / Comment DHW Pipe Insulation	<i>Units</i> Each	Q ty 1	Estimated	<u> </u>	Qty	Actual	
Measure 2 DW Comment INSULA # Material / Labor 1 Insulation 2 Labor	ATE FIRST 2FT OF HOT Description / Comment DHW Pipe Insulation	<i>Units</i> Each	Q ty 1	Estimated	<u> </u>	Qty	Actual	Inspected
Measure 2 DW Comment INSULA # Material / Labor 1 Insulation 2 Labor	ATE FIRST 2FT OF HOT Description / Comment DHW Pipe Insulation	Units Each Each	Qty 1 1	Estimated	<u> </u>		Actual	
Measure 2 DW Comment INSULA # Material / Labor 1 Insulation 2 Labor	ATE FIRST 2FT OF HOT Description / Comment DHW Pipe Insulation	Units Each Each	Qty 1 1	Estimated Unit Cost	<u> </u>		Actual Unit Cost	
Measure 2 DW Comment INSULA # Material / Labor 1 Insulation 2 Labor Other Detail	ATE FIRST 2FT OF HOT Description / Comment DHW Pipe Insulation	Units Each Each	Qty 1 1	Estimated Unit Cost	<u> </u>		Actual Unit Cost	
Measure 2 DW Comment INSULA # Material / Labor 1 Insulation 2 Labor Other Detail	ATE FIRST 2FT OF HOT Description / Comment DHW Pipe Insulation	Units Each Each	Qty 1 1	Estimated Unit Cost	<u> </u>		Actual Unit Cost	

Client Name: Client ID: 14014SO2325 Alt. Client ID: BEDFORD

Work Order (Bid Form) Work Order Name: 14014SO2325 DOE Weatherization Assistant Version 8.5.0

Report Run On: 5/28/2010

Inspected

Measure 3 Flo	or Ins. R-19			Componen				Inspected
			-	Estimated			Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Insulation	Floor Insulation - Fiberglass Batts - R-19	SqFt	992					
2 Labor	Floor Insulation - Fiberglass Batts - R-19	SqFt	992					
Other Detail								
			Measur	e Sub Total:			Sub Total:	
Measure 4 DW	/H Tank Insulation			Componen	ts			Inspected
	/H Tank Insulation			Componen Estimated			Actual	Inspected
Comment	/H Tank Insulation Description / Comment	Units	Qty	•		Qty		Inspected Total
Comment		<i>Units</i> Each	Qty 1	Estimated		Qty	Actual	
# Material / Labor 1 Hot Water Equipment	Description / Comment			Estimated		Qty	Actual	
# Material / Labor 1 Hot Water Equipment	Description / Comment DHW Tank Insulation	Each	1	Estimated		Qty	Actual	
# Material / Labor Hot Water Equipment Labor	Description / Comment DHW Tank Insulation	Each	1	Estimated		Qty	Actual	
# Material / Labor Hot Water Equipment Labor	Description / Comment DHW Tank Insulation	Each	1	Estimated			Actual	
# Material / Labor Hot Water Equipment Labor	Description / Comment DHW Tank Insulation	Each	1	Estimated Unit Cost			Actual Unit Cost	

Report Run On: 5/28/2010

Measure 6 Fix Comment	Improper Venting (Cloth	es Dryer)	Componen	ts			Inspected
			Estimated			Actual		
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
Health and Safety Items	y Metal Flex	Each	1					
2 Labor	Labor	Hour	1					
Other Detail								
			Measur	e Sub Total:			Sub Total:	
	Other Problems (Walls)	AL COVE		Componen LVROOM Estimated			Actual	Inspected
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Other	RECEPTICAL COVERS	Each	4.9		70.07	4. y		7000
	Re-install switch box cover							
2 Labor	Labor	Hour	1					
Other Detail								
			Measur	e Sub Total:			Sub Total:	
Field Notes:			Measur	e Sub Total:			Sub Total:	
Field Notes:			Measur	e Sub Total:			Sub Total:	

Report Run On: 5/28/2010

Measure 8 Smo	ke Detector is Needed			Componen	ts		ı	nspected
Comment								
				Estimated			Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Health and Safety Items	Smoke / Carbon detector	Each	1					
2 Labor	Labor	Hour	1					
Other Detail								
] []		
			Measur	e Sub Total:]	Sub Total:	
Field Notes:								
	or Barrier Needed ement/Crawlspace)			Componen	ts		ı	Inspected
				Estimated	<u> </u>		Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Insulation	Basement / crawlspace vapor barrier	Each	1					
2 Labor	Labor	Hour	1					
Other Detail						7		
] []		
] []	Cub Total:	
			Measur	e Sub Total:		<u> </u>	Sub Total:	
Field Notes:								
	_							
		Work O	rder Gra	nd Total:		Gran	d Total:	

Report Run On: 5/28/2010